From: Meyer, John

To: <u>Gray, David; Taheri, Diane; Bokun, Lisa</u>

Cc: Edlund, Carl; Phillips, Pam; Sanchez, Carlos; Miller, Garyg; Walters, Donn

Subject: San Jacinto Update 03/14/16 pm

Date: Monday, March 14, 2016 4:51:00 PM

Update as of 4:00 pm 3/14/16

Rock placement continued by the PRPs in the east cell today under EPA oversight to repair the deficient areas previously marked. The work is expected to be complete Tuesday. Additional probing is also being conducted beyond the repaired areas to assess the entire east cell. If additional areas are discovered, they will be added to the repair work currently underway.

Sent from my iPad

John C Meyer Remedial Branch Chief (6SF-R) Superfund Division 214.665.6742 214.460.5897 cell